1 Allée des Bouleaux -F-95110 SANNOIS
+33 (0)1 39 98 55 00
info@restagraf.com

CENTERING DEVICE DOOR WINDOW

Item code	Number of References	Number of pieces	Conditioning
12467	1	6	BAG

Materials
POLYACETAL

Manufacturer correspondence*	
FIAT	1360834080

* Non contractual information given as indication